

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402057734

Date Received:  
05/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900144

Inspection Date: 03/26/2019

FIR Submit Date: 04/08/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306821

Location Name: HJERMSTAD GAS UNIT A-M34N8W Number: 28SWNE County: LA PLATA

Qtrqr: SWNE Sec: 28 Twp: 34N Range: 8W Meridian: M

Latitude: 37.164856 Longitude: -107.720124

FACILITY - API Number: 05-067- -00 Facility ID: 268736

Facility Name: HJERMSTAD A Number: 3

Qtrqr: SWNE Sec: 28 Twp: 34N Range: 8W Meridian: M

Latitude: 37.164856 Longitude: -107.720124

CORRECTIVE ACTIONS:

1 CA# 123987

Corrective Action: Remove and properly dispose of kochia debris.

Date: 05/10/2019

Response: CA COMPLETED

Date of Completion: 05/03/2019

Operator  
Comment:

Weed debris has been removed from location see attached.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 123996

Corrective Action: Stabilize the Salt Creek stream crossing increase the conveyance capability so that it is capable of conveying flows during significant runoff events. Crossing should be constructed to ensure that culvert inlets and outlets are also stabilized using methods such as angular rock placement and installation of geotextiles. See CDOT recommendations for outlet protection.

Date: 05/03/2019

Response: CA COMPLETED

Date of Completion: 05/03/2019

Operator Comment: The road and crossing in this inspection is not a BPX installed road. This is the private residence drive way/access road installed by residence. BPX has no authority to modify or address issues on this road, only the access off this road directly into the well pad. However, the landowner did address the culverts and wash out issues with their driveway. This can be seen in the attached document.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action for weed debris completed by BPX see attached. Culverts and private drive way/resident access road was addressed by the residents. See attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 5/29/2019 10:12:02 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402057757	CA completion photos
-----------	----------------------

Total Attach: 1 Files