

Final Reclamation Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 333204

Inspection Document #: 697500169

Weld County, CO

NENE Section 11 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GRANT BROTHERS 41-11 #1
Location ID: 333204



Photo 1. Photo taken from the well location, facing North. This location is not in compliance with Rule 1004 vegetative standards, as there are bare patches with weedy, annual vegetation (Kochia).



Photo 2. Photo taken from the well location, facing South. Operator has failed to remove all equipment from location.

Inspection Photos

Location Name: GRANT BROTHERS 41-11 #1

Location ID: 333204



Photo 3. Photo taken from the tank battery location, facing South. Operator has failed to remove equipment from location.

Inspection Photos
Location Name: GRANT BROTHERS 41-11 #1
Location ID: 333204



Photo 4. Photo taken from the tank battery location, facing North. This location is not in compliance with Rule 1004 vegetative standards, as the location is dominated by weedy, annual vegetation (Kochia).

Inspection Photos
Location Name: GRANT BROTHERS 41-11 #1
Location ID: 333204



Photo 5. Reference photo taken northwest of the location, facing West.