

Final Reclamation Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 333204

Inspection Document #: 697500171

Weld County, CO

NENE Section 11 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WINFREY #41-11
Location ID: 333204



Photo 1. Photo taken from the tank battery location, facing South. Operator has failed to remove equipment from location.

Inspection Photos
Location Name: WINFREY #41-11
Location ID: 333204



Photo 2. Photo taken from the tank battery location, facing North. This location is not in compliance with Rule 1004 vegetative standards, as the location is dominated by weedy, annual vegetation (Kochia).

Inspection Photos
Location Name: WINFREY #41-11
Location ID: 333204



Photo 3. Reference photo taken northwest of the location, facing West.