

Inspection Photos
Location Name: BASHOR PC AA /17-18
Location #: 419804



Photo #1

Bashor PC AA 17-02D (05-123-32359) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor PC AA 17-18 (05-123-32358) Wellsite
Temporarily Abandoned | TA

Inspection Photos
Location Name: BASHOR PC AA /17-18
Location #: 419804



Photo #3

Bashor PC AA 17-02D, 17-18 – Battery Site

Abandoned – MOST equipment removed

Unused gas meter runs (2)

Unused riser & signage



Photo #4

Bashor PC AA 17-02D, 17-18 – Battery Site

Abandoned – MOST equipment removed

Unused gas meter runs (2)

Unused riser & signage