

Pit Status Evaluation Form

Pit Overview:

| | |
|--|-------------------------------|
| Pit Name: STATE 1-7 | Facility ID: 114309 |
| Current Status: Unknown | Status Date: 9/23/1999 |
| Current Operator: CORAL-CENTRAL OPERATING INC / 20263 | |
| Updated Operator: STARLIGHT RESOURCES LLC - 81825 | |
| Form 15 Pit Permit Doc #: NA | Permit Date: NA |
| Related Facilities: API # 05-001-07388, 001-07404, 001-07528, 001-07579, 001-07744, 001-07908, 001-07934. Location ID 376169. | |

| | | | |
|--|-------------------|--------------------|------------|
| County: Adams | | | |
| Township: 1S | Range: 67W | Section: 16 | QQ: |
| Original Latitude/ Longitude: | | / | |
| Updated Latitude/ Longitude: 39.962991 | | / -104.902805 | |
| Basis for Location Change: | | | |
| Location created at tank battery (historic aerial imagery) | | | |

Pit Inspection/Information Request:

| | |
|---|--------------------|
| Field Inspection Date: | Document #: |
| Pit Still Present in Field: No | |
| Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below) | |
| Inspection Notes: | |
| | |
| Operator Required to Submit Form: NA | Due Date: |
| Form Request Sent To: | Sent Date: |

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 583094 | Date: 2/16/1989 |
| | Doc #: 200070937 | Date: 05/17/2005 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314547 | Date: 2/11/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 112655 (status closed) | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Associated wells PA from 7/18/1995-6/21/2004. Battery inspections associated with State of Colorado #1 (001-07388)- passed final inspection 5/17/2005.

Pit Status Review Summary:

Duplicate of pit 112655. Based on records review any pits on location were removed prior to 1998 pit inventory inquiries. Tank battery site and associated well site passed final inspection 5/17/2005. Pit status has been changed to Closed.