

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402054535

Date Received:  
05/30/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Bill Espinosa

303-829-4982

billespinosa30@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685100891

Inspection Date: 05/02/2019

FIR Submit Date: 05/02/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC

Company Number: 74165

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 320177

Location Name: WALKER ANN-62S62W Number: 29NWSW County: ADAMS

Qtrqr: NWS Sec: 29 Twp: 2S Range: 62W Meridian: 6  
W

Latitude: 39.845250 Longitude: -104.355350

FACILITY - API Number: 05-001- -00 Facility ID: 202912

Facility Name: WALKER ANN Number: 2

Qtrqr: NWS Sec: 29 Twp: 2S Range: 62W Meridian: 6  
W

Latitude: 39.845250 Longitude: -104.355350

CORRECTIVE ACTIONS:

1 CA# 124840

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/19/2018

Response: CA COMPLETED

Date of Completion: 05/24/2019

Operator Comment: Oil stained soil has been cleaned up and removed. Wellhead fittings inspected and tightened to ensure good mechanical condition per Rule 605.d. See photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 124841

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 11/19/2018

Response: CA COMPLETED

Date of Completion: 05/24/2019

Operator Comment: Gas motor exchanged with a rebuilt motor. Soil stained with lube oil was removed and disposed of per Rule 907.e. Stained oil associated with exhaust also removed and disposed of. See photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All oil staining addressed. Pumping unit gas motor swapped out. Gas motor lube oil leak issues corrected. See photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: \_\_\_\_\_

Title: Manager/Owner

Date: 5/30/2019 1:17:56 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402059327	New rebuilt engine. Stained oil removed.
402059330	New rebuilt engine. Stained oil removed.
402059331	Cleaned up wellhead

Total Attach: 3 Files