

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:12:32
38.43886N 103.05999W

Stained soil around wellhead has been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Stained soil temporarily stored in lined containment on location.



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:17:02
38.43886N 103.05958W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:17:48
38.43919N 103.05963W



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:18:07
38.43926N 103.05972W



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:18:42
38.43935N 103.05946W

Unused equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:19:36
38.43954N 103.05903W

Unused equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:20:01
38.43975N 103.05892W

Unused equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



May 29, 2019 12:20:06
38.43974N 103.05890W

Unused equipment stored on location.



Location Name: Frazee 2-6 #1 API: 061-06365 Inspection Date: 5/29/2019



Dump truck filled with oil stained soil parked on location.

