

Inspection Photos  
UNOCAL-66S96W 4NESW  
Location # 335778  
CAERUS PICEANCE LLC 10456



Location battery sign.

Location photo

Inspection Photos  
**UNOCAL-66S96W 4NESW**  
Location # 335778  
**CAERUS PICEANCE LLC 10456**



**Well sign has been replaced.**

Inspection Photos  
**UNOCAL-66S96W 4NESW**  
Location # 335778  
**CAERUS PICEANCE LLC 10456**



**Unused buried 1/2" tubing ran from separator to well 23-4D**

**Unused buried 1/2" tubing ran from separator to well 23-4D**

Inspection Photos  
**UNOCAL-66S96W 4NESW**  
Location # 335778  
**CAERUS PICEANCE LLC 10456**



**Rathole has subsided and is exposed.**



**Rathole has subsided and is exposed.**