

Pit Status Evaluation Form

Pit Overview:

Pit Name: Federal 26-8	Facility ID: 118428
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: Benson Mineral Group Inc. / 7640	
Updated Operator:	
Form 15 Pit Permit Doc #: 383614	Permit Date: 08/02/1988
Related Facilities: Federal 26-8 Well API 05-123-13741, Location ID 408334	

County: Weld			
Township: 8N	Range: 59W	Section: 26	QQ: SENE
Original Latitude/ Longitude: 40.634626 / -103.936997			
Updated Latitude/ Longitude: 40.634461 / -103.937275			
Basis for Location Change:			
Site Sketch 383620 and estimated based on location scar in aerials			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 383614 | Date: 08/02/1988 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: | Date: |
| Doc #: 218381 | Date: 08/15/1988 |
| Doc #: 200073194 | Date: 06/22/2005 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input checked="" type="checkbox"/> Form 4 Sundry Notice – Doc #: 218376 | Date: 11/12/1991 |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 04/07/1989

Timing of Pit Closure:

Pit closed with plugging and abandonment of well in 1989

Pit Status Review Summary:

Pit permit and associated diagrams indicate pit was location in southwest corner of well pad. Well was plugged in 1989 and pit closed in accordance with COGCC Rules in effect at closure. Site passed final reclamation inspection in 1991 and 2005.