

Inspection Photos
Location Name: Larson 20-11
Location ID: 302243



Photo 1: PREVIOUS photo of overgrown weeds at wellhead.

Photo 2: CURRENT photo of weeds removed.

Inspection Photos
Location Name: Larson 20-11
Location ID: 302243



Photo 3: PREVIOUS photo of no emergency contact



Photo 4: CURRENT photo of sign with emergency contact



Inspection Photos
Location Name: Larson 20-11
Location ID: 302243



Photo 5: Centralized Tank Battery



Photo 6: No NFPA Placard



Inspection Photos
Location Name: Larson 20-11
Location ID: 302243



Photo 7: Stained soil



Photo 8: Erosion from stormwater



Inspection Photos
Location Name: Larson 20-11
Location ID: 302243



Photo 9: Erosion from stormwater