

Inspection Photos
Location Name: SINJIN-66N65W /36NESE
Location #: 328685



Photo #1

Sinjin E 36-9 (API # 05-123-16303) Wellsite

Shut-In | SI

Unused Equipment



Photo #2

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down

Mud w/ puddles from prior rain