

Inspection Photos
Location Name: SINJIN E-66N65W /36NESW
Location #: 305188



Photo #1

Sinjin E 36-25 (API # 05-123-22619) Wellsite

Shut-In | SI

Unused Equipment

No LTSl or Decommission TA/Sl tags per agreement



Photo #2

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down

Mud w/ puddles from prior rain