

Inspection Photos

Operator: Kinder Morgan
Location/API #: 033-06132
Date: 5-30-2019



Photo 1. View of the northern project area from the northwestern edge facing eastward.



Photo 2. View of erosional rilling within the eastern project area.



Photo 3. View of the southern project area from the southwestern edge facing eastward.