

Inspection Photos

API: 05-071-06223

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 6/3/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 6/3/2019

Inspection Photos



Photo 1. The main southfork road has areas of road damage that needs to be graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 6/3/2019

Inspection Photos



Photo 2. Facing southwest toward the location. There are erosion issues coming off the pad surface and is depositing sediment into the culvert along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 6/3/2019