

Inspection Photos

Loc#323788

Operator: Mustang Resources

Inspection Number: 692401002

Inspection Date: 5/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location from entry.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Res API#045-07675



Photo#2:
Unused area at North end of Pad.



Photo#3:
Debris Weeds in Interim areas.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Res Loc# 323788