

# *Inspection Photos*

*Loc#323868*

*Operator: Terra*

*Inspection Number: 692401000*

*Inspection Date: 5/21/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to Northeast.

May 21, ,2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Juhan Loc#323868



Photo#2

View to east over area no longer needed for use.

May 21, ,2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Juhan Loc#323868





Photo#3:  
Area in back (to NW) of Separators is being used for  
storage of Material stockpiles

May 21, ,2019



Photo#4:  
Wattles installed as perimeter controls.





Photo#5:  
Cellar grate (cover) has a gap on Southeast side.



Photo#6:

May 21, ,2019