

Inspection Photos  
Location Name: GOPHER 31-9  
API#: 05-071-09599  
INSP. #: 695100797



**PHOTO 1: WELLHEAD**

**PHOTO 2: WELL SIGN/ CURRENT OPERATOR IS NOT POSTED ON WELL SIGN. POST CURRENT OPERATOR ON WELL SIGN IN ACCORDANCE WITH 210 SERIES RULES. CA DATE 8/4/19.**

Inspection Photos  
Location Name: GOPHER 31-9  
API#: 05-071-09599  
INSP. #: 695100797



Colorado Oil & Gas Conservation Commission  
37.18967, -104.78332, 2185.0m, 46°  
2019/06/04 16:17:00



Colorado Oil & Gas Conservation Commission  
37.18967, -104.7833, 2186.0m, 13°  
2019/06/04 16:17:35

**PHOTO 3: AREA OF IMPACTED GRAVEL AROUND WELLHEAD APP. 2' BY 4' IN SIZE. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 7/4/19**

**PHOTO 4: HYDRAULIC FITTING APPEARS TO BE SEEPING FLUID. Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation" CA DATE 7/4/19**