

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2019

Submitted Date:

06/05/2019

Document Number:

680305015

**FIELD INSPECTION FORM**

Loc ID 336746 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 7950 JOHN T WHITE ROAD  
City: FORT WORTH State: TX Zip: 76120

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone        | Email                         | Comment |
|----------------|--------------|-------------------------------|---------|
| Fisher, Jeremy | 970-854-4733 | Jeremy_Fisher@omimexgroup.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 278961      | WELL | PR     | 09/13/2005  | GW         | 125-09364 | FERGUSON 7-9-5-45 | PR          |

**General Comment:**

[Routine Site Inspection](#)

**Location**

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Lease Road:</b> |   |  |       |
| Type               | Access  |  |       |
| comment:           | Two track grassland - maintain lease road/loose sandy soils |  |       |
| Corrective ActionL |   |  | Date: |

Overall Good:

|                      |              |  |       |
|----------------------|--------------|--|-------|
| <b>Signs/Marker:</b> |              |  |       |
| Type                 | WELLHEAD     |  |       |
| Comment:             | Satisfactory |  |       |
| Corrective Action:   |              |  | Date: |

|                                  |              |  |             |
|----------------------------------|--------------|--|-------------|
| <b>Emergency Contact Number:</b> |              |  |             |
| Comment:                         | Satisfactory |  |             |
| Corrective Action:               |              |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |             |  |       |
|--------------------|-------------|--|-------|
| <b>Fencing/:</b>   |             |  |       |
| Type               | PUMP JACK   |  |       |
| Comment:           | Steel panel |  |       |
| Corrective Action: |             |  | Date: |

|                          |           |  |                 |
|--------------------------|-----------|--|-----------------|
| <b>Equipment:</b>        |           |  | corrective date |
| Type: Pump Jack          | # 1       |  |                 |
| Comment:                 |           |  |                 |
| Corrective Action:       |           |  | Date:           |
| Type: Vertical Separator | # 1       |  |                 |
| Comment:                 |           |  |                 |
| Corrective Action:       |           |  | Date:           |
| Type: Prime Mover        | # 1       |  |                 |
| Comment:                 | NG engine |  |                 |
| Corrective Action:       |           |  | Date:           |
| Type: Gas Meter Run      | # 1       |  |                 |
| Comment:                 |           |  |                 |
| Corrective Action:       |           |  | Date:           |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Venting:</b> |  |  |  |
| Yes/No          |  |  |  |
| Comment:        |  |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 278961 Type: WELL API Number: 125-09364 Status: PR Insp. Status: PR

**Producing Well**

Comment: [GW](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | In Process      | Other                   | In Process            |               |                          |         |

Comment: Use BMP's for erosion management. Maintain lease road

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT