

Inspection Photos
Location Name: Ocho LD Pad
Location ID: 449174



Colorado Oil and Gas Conservation Commission
39.98347, -104.91259, 1564.1m
Jun 5, 2019 12:02:17



Colorado Oil and Gas Conservation Commission
39.98353, -104.91261, 1568.5m
Jun 5, 2019 12:02:37

Photo 1 loc signs

Photo 2 tracking pad into location

Inspection Photos
Location Name: Ocho LD Pad
Location ID: 449174



Photo 3 tracking pad to location impacted with sediment

Photo 4 Sediment tracking onto HWY 7 from Monaco street

Inspection Photos
Location Name: Ocho LD Pad
Location ID: 449174



Photo 5 Sediment tracking onto HWY 7 from Monaco street

Photo 6 Sediment tracking onto HWY 7 from Monaco street