

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08295
Date: 6-4-2019



Photo 1. View of the southern project area from the southwestern edge facing eastward.



Photo 2. View of wood debris and pallets within the northern portion of the project area.



Photo 3. View of erosional channel and sediment deposition on the western edge of the access road.