

Inspection Photos

06/04/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 447523

Inspection Doc. Number: 696200155
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 1: Photo taken from southwest end of the location, facing north. Photo shows reclamation equipment/facilities remaining on the location . Operator has failed to conduct final reclamation on the location.



Photo 2: Photo taken from southwest end of the location, facing east. Photo shows reclamation equipment/facilities remaining on the location . Operator has failed to conduct final reclamation on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 3: Photo taken from the south end of the location. Photo shows areas where Diffuse Knapweed is maturing.



Photo 4: Photo taken from the south end of the location. Photo shows areas where Diffuse Knapweed is maturing.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 5: Photo taken from south end of the location, facing south. Photo shows reclamation equipment/facilities remaining on the location. Operator has failed to conduct final reclamation on the location.



Photo 6: Photo taken from south end of the location, facing north. Photo shows reclamation equipment/facilities remaining on the location. Operator has failed to conduct final reclamation on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 7: Photo shows stained/contaminated soils at tank on the southeast end of the location.



Photo 8: Photo taken from the east end of the location. Photo shows areas where Diffuse Knapweed is maturing

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 9: Photo taken from east end of the location, facing west. Photo shows reclamation equipment/facilities remaining on the location. Operator has failed to conduct final reclamation on the location.



Photo 10: Photo taken from east end of the location, facing northwest. Photo shows reclamation equipment/facilities remaining on the location. Operator has failed to conduct final reclamation on the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 11: Photo taken from the adjacent areas, east of the location.



Photo 12: Photo taken from the adjacent areas of the location. Photo shows areas where Diffuse Knapweed have spread from the location remain established.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 13: Photo taken from the adjacent areas of the location. Photo shows areas where Diffuse Knapweed have spread from the location remain established.




Photo 14: Photo taken from the adjacent areas of the location. Photo shows areas where Diffuse Knapweed have spread from the location remain established.