

Inspection Photos

06/04/2019

Operator: DIVERSIFIED OPERATING
CORPORATION # 24461

Location ID: 408218

Inspection Doc. Number: 696200172
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: DIVERSIFIED OPERATING CORPORATION # 24461

Location ID: 408218



Photo 1: Photo taken from east end of the location, facing west. Photos shows fence remaining at the location and what appears to be ~15 monitoring wells remaining.



Photo 2: Photo taken from the location, facing west. Photo shows what appears to be ~15 monitoring wells remaining. Photo also shows location has not achieved a uniform vegetative establishment on the location in accordance with 1004.a.

Inspection Photos

Operator Name: DIVERSIFIED OPERATING CORPORATION # 24461

Location ID: 408218



Photo 3: Photo taken from the location, facing south. Photo shows access road remains and has not been reclaimed.



Photo 4: Photo taken from the location, facing west. Photo shows access road remains and has not been reclaimed.

Inspection Photos

Operator Name: DIVERSIFIED OPERATING CORPORATION # 24461

Location ID: 408218



Photo 5: Photo taken from the access road, facing northwest. Photo shows section of access road that crosses a drainage. Photo shows erosion degradation and sediment transport off road. Access road remains and has not been reclaimed

