

Maralex Resources Inc.
API # 05-077-08622
Inspection # 696600080



Photo #1 Photo of location from S entrance of location

Maralex Resources Inc.
API # 05-077-08622
Inspection # 696600080



Photo #2 Photo from N entrance

Maralex Resources Inc.

API # 05-077-08622

Inspection # 696600080



Photo #3 Photo showing removal of all pipe that was left on location



Photo #4 Photo showing removal of all pipe that was left on location