

# Inspection Photos

API: 05-099-06215

Operator: BERRY ENERGY INC

Inspection Date: 6/4/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019

## Inspection Photos



**Photo 1.** A two track access road remains to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 2.** A culvert remains along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 3.** There is erosion occurring along the access road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019

## Inspection Photos



**Photo 4.** Facing northwest toward the location. This area is bare approximately 150' x 100'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 5.** Facing toward the southwest toward the cut slope. The location has not been recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019

## Inspection Photos



**Photo 6.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 7.** There is a single pipe riser that remains at the north side of location. Another riser further north may be an active line per previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 8.** The View of possible active ling north of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019



## Inspection Photos



**Photo 9.** Facing south toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-099-06215 | Date: 6/4/2019