

Inspection Photos

API: 05-099-06911

Operator: RAMSEY PROPERTY MANAGEMENT LLC

Inspection Date: 6/4/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 1. Facing southeast along the access road which has revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 2. Facing east at the location. Vegetation consists of Pas smi, Spr cry, Art fil, Bou gra, among other natives and weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 2. Facing north at the location. Vegetation consists of Pas smi, Spr cry, Art fil, Bou gra, among other natives and weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 4. Facing west at the location. Vegetation consists of Pas smi, Spr cry, Art fil, Bou gra, among other natives and weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 5. Facing south at the location. Vegetation consists of Pas smi, Spr cry, Art fil, Bou gra, among other natives and weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019

Inspection Photos



Photo 6. Facing south at the surrounding reference. Vegetation consists of Pas smi, Spr cry, Art fil, Bou gra, among other natives and weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06911 | Date: 6/4/2019