

Inspection Photos

API: 05-061-06490

Operator: CHEMCO INC

Inspection Date: 6/5/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019

Inspection Photos



Photo 1. There is a tank battery west of the location at Lat/Long:38.45002,-102.43552.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019

Inspection Photos



Photo 2. There is cement blocks, pipe riser, and electric utilities near the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019

Inspection Photos



Photo 3. Site of the well near a grain silo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019

Inspection Photos



Photo 4. There is a bare area near the well site approximately 30'x20'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019

Inspection Photos



Photo 5. Facing south toward location site near grain silo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06490 | Date: 6/5/2019