

# Inspection Photos

API: 05-061-06684

Operator: CITATION OIL & GAS

Inspection Date: 6/5/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-061-06684 | Date: 6/5/2019

## Inspection Photos



**Photo 1.** Facing west toward the location.. Crop has not established in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06684 | Date: 6/5/2019



## Inspection Photos



**Photo 2.** Facing east toward the location. There are areas where the crop has not established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06684 | Date: 6/5/2019



## Inspection Photos



**Photo 3.** Facing south toward the surrounding crop cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06684 | Date: 6/5/2019