

Inspection Photos

API: 05-061-06892

Operator: MULL DRILLING COMPANY

Inspection Date: 6/5/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019

Inspection Photos



Photo 1. Facing east along the former access road. Crop has established a uniform cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019

Inspection Photos



Photo 2. Facing north toward the location. Crop has established a uniform cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019

Inspection Photos



Photo 4. Facing south toward the location. Crop has established a uniform cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019

Inspection Photos



Photo 5. Facing east toward the location. Crop has established a uniform cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019

Inspection Photos



Photo 6. Facing west toward the location. Crop has established a uniform cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06892 | Date: 6/5/2019