

Inspection Photos

Loc#311683

Operator: Ursa

Inspection Number: 692401053

Inspection Date: 5/30/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Hoffmeister Loc#311683



Photo#2:
Cellar needing more complete cover.



Photo#3:
Cellar needing more complete cover.

May 30, ,2019




Photo#4:
Equipment and stockpile stored adjacent to Wells.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Hoffmeister Loc#311683



Photo#5:
Vegetation along the encircling perimeter of location consists of Cheat grass and Kochia.

May 30, ,2019



Photo#6:
Vegetation along the encircling perimeter of location consists of Cheat grass and Kochia.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Hoffmeister Loc#311683