

Final Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 309839

Inspection Document #: 697500182

Weld County, CO

NWNE Section 16 T4N R64W


Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RYANN STATE C #16-27
Location ID: 309839



Aerial imagery taken in 2017. Aerial imagery shows two areas circled in yellow. The Ryann State C 16-27 well was serviced by the northern tank battery circled in yellow.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 1. Photo taken from the southern portion of the northern tank battery, facing West. Photo illustrates no equipment was observed at the location. The Ryann State C 16-27 well was plugged 11/8/2018. Per Rule 1004, Operator shall make every reasonable effort to perform final reclamation before the next local growing season. It appears the Operator could have performed Final Reclamation during the 2019 Spring seeding window but failed to do so.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 2. Photo taken from the southern portion of the northern tank battery, facing North. See comments under Photo 1.