

# Interim Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 329335

Inspection Document #: 697500187

Weld County, CO

SWSW Section 10 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: RICHARDSON #10-13  
Location ID: 329335



Aerial imagery taken in 2011. Aerial imagery shows a disturbance area around the wellhead that is not reflective of reference area vegetation.

Inspection Photos  
Location Name: RICHARDSON #10-13  
Location ID: 329335



**Photo 1.** Photo taken adjacent to the well location, facing South. Photo illustrates a disturbance that is not reflective of reference area vegetation.



Inspection Photos  
Location Name: RICHARDSON #10-13  
Location ID: 329335



**Photo 2.** Photo taken adjacent to the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: RICHARDSON #10-13  
Location ID: 329335



**Photo 3.** Photo taken adjacent to the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: RICHARDSON #10-13  
Location ID: 329335



**Photo 4.** Reference photo taken west of the well location, facing West. See comments under Photo 1.