

# *Inspection Photos*

*Loc#311621*

*Operator: Ursa*

*Inspection Number: 692401045*

*Inspection Date: 5/30/19*






**Photo#1:**  
Overview of Location to Southeast. Insert of un-marked Anchor

May 30, ,2019



Photo#2:  
Vegetation in Interim Reclamation areas has failed.



Photo#3:  
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019



**Photo#4:**  
Vegetation in Interim Reclamation areas has failed.

**Photo#5:**  
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019