

Inspection Photos

Loc#336027

Operator: Ursa

Inspection Number: 692401047

Inspection Date: 5/30/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Coloroso Loc#336027



Photo#2:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019



Photo#3:
Vegetation in Interim Reclamation areas has failed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Coloroso Loc#336027



Photo#4:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019



Photo#5:
Vegetation in Interim Reclamation areas has failed.