

Inspection Photos

Loc#336017

Operator: Ursa

Inspection Number: 692401051

Inspection Date: 5/30/19





Photo#1:
Overview of Location from Entry. Insert of Subsidence.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa North Bank E Loc#336017



Photo#2:
Vegetation in Interim Reclamation areas has failed.



Photo#3:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa North Bank E Loc#336017



Photo#4:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019