

Inspection Photos

Loc#336016

Operator: Ursa

Inspection Number: 692401079

Inspection Date: 5/30/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry.

May 30, ,2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa North Bank A Loc#336016



Photo#2:
Vegetation in Interim Reclamation areas has failed.



Photo#3:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019



Photo#4:
Vegetation in Interim Reclamation areas has failed.



Photo#5:
Vegetation in Interim Reclamation areas has failed.

May 30, ,2019