

**Inspection Photos**  
**Location Name: Dorothy #1 Location ID 319436**  
**Inspection Date: 6/6/2019**



40.59344, -103.90481, 4737.5ft  
06/06/2019 12:49:13

**Photo 1 – Tubing stacked on location.**



40.59311, -103.90463, 4744.1ft  
06/06/2019 12:52:47

**Photo 2 – Cement (unused or returns) on location.**



**Inspection Photos**  
**Location Name: Dorothy #1 Location ID 319436**  
**Inspection Date: 6/6/2019**



**Photo 3 – Produced water pit, not closed.**



**Photo 4 – Oily soil stockpiled on location.**



**Inspection Photos**  
**Location Name: Dorothy #1 Location ID 319436**  
**Inspection Date: 6/6/2019**



**Photo 5 – Oily soil present in pit berms.**



**Photo 6 – Oily soil present in pit berms.**

