

Inspection Photos
Location Name: CHINOOK-67N57W /14NWNW
Location #: 305168



Photo #1
Chinook #1 (05-123-22590) Wellhead
Shut-In | SI
Weeds
Bradenhead NOT plumbed to surface
from prior insp.



Photo #2
Chinook #1 Wellhead
Shut-In | SI
Weeds
Bradenhead NOT plumbed to surface

Inspection Photos
Location Name: CHINOOK-67N57W /14NWNW
Location #: 305168



Photo #3
Northrup 1-14, 2-14, Chinook #1 Battery
Shut-down
from prior insp.



Photo #4
Northrup 1-14, 2-14, Chinook #1 Battery
Shut-down

Inspection Photos
Location Name: CHINOOK-67N57W /14NWNW
Location #: 305168



Photo #5
Chinook #1 Pump jack
Shut-In | SI
Weeds
from prior insp.



Photo #6
Chinook #1 Pump jack
Shut-In | SI
Weeds

Inspection Photos

Location Name: CHINOOK-67N57W /14NWNW

Location #: 305168



Photo #7
Chinook #1 Access Road
Weeds
from prior insp.



Photo #8
Chinook #1 Access Road
Weeds

Inspection Photos
Location Name: CHINOOK-67N57W /14NWNW
Location #: 305168



Photo #9
Chinook #1 Location
Weeds
from prior insp.



Photo #10
Chinook #1 Location
Weeds

Inspection Photos
Location Name: CHINOOK-67N57W /14NWNW
Location #: 305168



Photo #11
Chinook #1 Tank Area
Maintenance & H2O Tanks
Weeds
from prior insp.



Photo #12
Chinook #1 Tank Area
Maintenance & H2O Tanks
Weeds