

Laramie Energy LLC
API # 05-077-09288
Inspection # 696600104



Photo #1 Photo from entrance of location.

Laramie Energy LLC
API # 05-077-09288
Inspection # 696600104



Photo #2 Well heads and signs on location.



Photo #3 Photo taken of tank battery

Laramie Energy LLC
API # 05-077-09288
Inspection # 696600104



Photo #4 Holes in Tank liner.

