

Inspection Photos

06/10/2019

Operator: STANDLEY* ROBERT K DBA OTIS
ENERGY - 81720

Location ID: 404381
Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: STANDLEY* ROBERT K DBA OTIS ENERGY - 81720

Location ID: 404381



Photo 1: Photo taken from the west end of the pit, facing east. Photo shows pit has not been reclaimed. Photo also shows possible salt issues at the pit wall



Photo 2: Photo taken from the southwest corner of the pit. Photo shows possible soil stockpile from the pit.

Inspection Photos

Operator Name: STANDLEY* ROBERT K DBA OTIS ENERGY - 81720

Location ID: 404381



Photo 3: Photo taken from the north end of the pit, facing southeast. Photo shows pit has not been reclaimed. Photo also shows possible salt issues at the pit wall



Photo 4: Photo taken from the north end of the pit, facing southwest. Photo shows pit has not been reclaimed. Photo also shows possible salt issues at the pit wall