

Inspection Photos
Loc#335359
Operator: Caerus
Insp#692401081
Inspection Date: 5/31/2019





Photo#1:
Overview of Location from entry.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335359



Photo#2:
Vegetation at Wellhead.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335359



Photo#3:
Erosion occurring on Cut Slope.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335359



Photo#4:
Disturbance on Cut slope.



Photo#5:
Sediment migration concerns.

May 31, 2019



Photo#6:
Sediment migration concerns.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335359