

Inspection Photos
Loc#334942
Operator: Caerus
Insp#692401082
Inspection Date: 5/31/2019





Photo#1:
Overview of Location from entry.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Craig Loc#334942



Photo#2:
Washout at entry.

May 31, 2019



Photo#4:
Vegetation is well established.

May 31, 2019