

RG 13-1-398
API: 05-103-10605
Inspection: 679704452



Photo 1. Location.

RG 13-1-398
API: 05-103-10605
Inspection: 679704452



Photo 2. Incorrect api number on battery sign. Sign has 05-103-10597. Correct API is 05-103-10605.



Photo 3. Unmarked deadman.