

Inspection Photos
Location Name: RIVERSIDE 43-1 & TR
API#: 05-071-06966 & 07548
INSP. #: 695100839



PHOTO 1: ORIGINAL WELLHEAD



PHOTO 2: TR WELLHEAD

Inspection Photos

Location Name: RIVERSIDE 43-1 & TR

API#: 05-071-06966 & 07548

INSP. #: 695100839



PHOTO 3: ORIGINAL WELL SIGN



PHOTO 4: TR WELL SIGN




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: RIVERSIDE 43-1 & TR

API#: 05-071-06966 & 07548

INSP. #: 695100839



Colorado Oil & Gas Conservation Commission
37.19776, -104.83369, 2220.0m, 203°
2019/06/11 10:00:41



Colorado Oil & Gas Conservation Commission
37.19776, -104.83369, 2221.0m, 193°
2019/06/11 10:00:51

PHOTO 5: AREA OF IMPACTED SOIL APP. 6' BY 6' EXTENDING FROM SOUND WALL UNDER ENGINE SKID FOR ORIGINAL WELL. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 7/11/19.

PHOTO 6: STANDING OILY WATER IN ENGINE SKID FOR ORIGINAL WELL. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 7/11/19.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: RIVERSIDE 43-1 & TR

API#: 05-071-06966 & 07548

INSP. #: 695100839



PHOTO 7: TRASH FLOATING IN ORIGINAL WELL PIT. REMOVE TRASH IN COMPLIANCE WITH 603.f. CA DATE 7/11/19.