

Inspection Photos

Operator: Beeman Oil and Gas
Location/API #: 067-09390
Date: 6-7-2019



Photo 1. View of the project area from the northwestern corner facing center. Infestation of Russian knapweed present in the central portion of the working area.



Photo 2. View of the southern project area from the southwestern corner facing eastward.