

# Inspection Photos

API: 05-055-06035

Operator: OXY USA INC

Inspection Date: 6/11/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019

## Inspection Photos



**Photo 1.** Facing along the curve of the main road. There are numerous noxious weeds (Canada thistle) in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019



## Inspection Photos



**Photo 2.** The operator name on well sign is not legible.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019



## Inspection Photos



**Photo 3.** Facing northwest toward the fenced pit. There are numerous noxious weeds (Canada thistle) in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019



## Inspection Photos



**Photo 4.** Facing southeast near the pit area. There are numerous noxious weeds (Canada thistle) in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019