

Inspection Photos
Location Name: FACE OFF 23-24
API#: 05-071-07513
INSP. #: 695100877




PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: FACE OFF 23-24

API#: 05-071-07513

INSP. #: 695100877



PHOTO 3: TRASH IN PIT. COMPLY WITH RULE 603.f. CA DATE 7/12/19



PHOTO 2: TRASH IN PIT. COMPLY WITH RULE 603.f. CA DATE 7/12/19

Inspection Photos

Location Name: FACE OFF 23-24

API#: 05-071-07513

INSP. #: 695100877



PHOTO 5: APP. 3' BY 2' AREA OF IMPACTED SOIL NEAR WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/12/19.



PHOTO 6: APP. 1' ROUND AREA OF IMPACTED SOIL NEAR ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/12/19.