

## Inspection Photos

**Location Name:** D.O.C. SHOWERS-68N60W /32NWSW

**Location #:** 330667



Colorado Oil & Gas Conservation Commission  
40.61679, -104.12397, 1477.0m, 70°  
06/12/2019 02:53:56 PM

**Photo #1**

**D.O.C. Showers 32-12-10 (05-123-19437) Wellsite**

**Plugged & Abandoned | PA**

**Reclamation progressing**

**≈ 25 yds.**



Colorado Oil & Gas Conservation Commission  
40.61162, -104.12343, 1485.0m, 305°  
06/12/2019 02:41:02 PM

**Photo #2**

**D.O.C. Showers 32-12-10, Showers 32-5-7**

**Former Battery - Inactive**

**Shut-down**

## Inspection Photos

Location Name: D.O.C. SHOWERS-68N60W /32NWSW

Location #: 330667



**Photo #3**

**D.O.C. Showers 32-12-10, Showers 32-5-7**

Inactive Battery – H2O tank

***Berms are inadequate***

*from prior insp.*



**Photo #4**

**D.O.C. Showers 32-12-10, Showers 32-5-7**

Inactive Battery – H2O tank

***Berms NOW appear adequate***