

# Final Reclamation Inspection

June 10, 2019

Operator: Blue Chip Oil Inc- 8840

API: 05-123-13536

Inspection Document #: 697500205

Weld County, CO

NENE Section 25 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 1.** Photo taken from the western location, facing East. Photo illustrates the Operator performed final reclamation activities with the evidence of germination; however, it does not appear the Operator has performed weed management as weedy vegetation was observed throughout the location.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 2.** Photo taken from the western location, facing South. Photo illustrates weedy annual vegetation, mostly consisting of Kochia.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 3.** Photo taken from a portion of the western location, facing South. See comments under Photos 1 and 2.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 4.** Photo taken from the western location, facing West. Photo illustrates bares area with no germination of desirable species.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 5.** Photo taken along the western access road, facing East. See comments under Photos 1 and 2.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 6.** Photo taken from the eastern location, facing Southeast. See comments under Photos 1 and 2.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 7.** Photo taken from the eastern location, facing Northeast. See comments under Photos 1 and 2.



Inspection Photos  
Location Name: SLOAN #1  
API: 05-123-13536



**Photo 8.** Photo taken from the eastern location, facing East. See comments under Photos 1 and 2.