

Inspection Photos
Location Name: Vair Pad
Location ID: 433400



Photo 1: Sign at access road



Photo 2: Location



Inspection Photos
Location Name: Vair Pad
Location ID: 433400



Photo 3: Tank Battery



Photo 4: No BBLs on produced water



Inspection Photos
Location Name: Vair Pad
Location ID: 433400



Photo 5: Stained soil