

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2019

Submitted Date:

06/17/2019

Document Number:

697600085**FIELD INSPECTION FORM**Loc ID 423682 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423677	WELL	PR	01/01/2018	OW	123-33668	VARRA P31-76HN	EI
423682	LOCATION	AC	01/01/2018		-	VARRA P31-76HN	EI
423687	WELL	PR	01/01/2018	OW	123-33675	VARRA P31-74HN	EI

General Comment:[production facilities not on location with wells and only wells inspected in this document](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	CH3OH container		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	120 gallons
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Inspected Facilities									
Facility ID:	423677	Type:	WELL	API Number:	123-33668	Status:	PR	Insp. Status:	EI
Facility ID:	423682	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	423687	Type:	WELL	API Number:	123-33675	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT